


Improvement	Order of Magnitude Cost
Fix sign mounting height and burned out bulb	Low
Install a 48" stop sign with break away mounting post	Low
Install crosswalk markings	Low
Install detectable warning surface	Low
Investigate the health of the Water Oak	Low
Refresh edge line paint	Low
Review sight distance at intersection	Low
Trim tree to improve sight distance	Low
Trim tree to improve sight line for flasher	Low



Road Safety Audit
Fort Johnson Road at Secessionville Road
and Fort Johnson Road at Camp Road

Short-Term Improvements:
Secessionville Road at Fort
Johnson Road

Figure 1