


Improvement	Order of Magnitude Cost
Remove scrub brush	Low
Install edge line pavement markings	Low
Improve sight distance	Low
Refresh crosswalk striping	Low



	Road Safety Audit Fort Johnson Road at Secessionville Road and Fort Johnson Road at Camp Road	Short-Term Improvements: Camp Road/Stone Post Road at Fort Johnson Road	Figure 4
--	--	--	-----------------